

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Adjoining vegetation/RoW



Fig C: The Leak Point after excavation



Fig D: Incident facility during repair