

Incident no - 2340807

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This form is to be completed and signed by all participating parties in the field

1. Company: SPLC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify):

3. Incident Details

i. Date of Incident: 04-05-2019 ii. Date first reported: 04-05-2019

iii. Date of first investigation: 07-05-2019

iv. Date of follow-up investigation: 14/05/2019

v. Time investigation started: 2.00 PM

vi. Estimated quantity spilled: 2 Bbls

4. Site Details

i. Site location: 14" Olefins recovery pipeline at a Refinery

ii. Position of Spill/Leak:

iii. Spill area:

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify):

iv. Structural Controls in Place:

- ☐ Barricade ☐ Trenches ☐ Bund Wall ☐ Surchurns ☐ Others (Specify): NA

5. Circumstances Around Spill Point

i. Visual observation of Hole Position:

- ☒ 0° Clock ☐ 10° Clock ☐ 20° Clock ☐ 30° Clock
☐ 40° Clock ☐ 50° Clock ☐ 60° Clock

ii. Type of Oil Contaminant:

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify):

iii. Facility:

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Blow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify):

iv. Cause of Spill:

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify):

v. Visible Sign of Third Party Interference:

- ☐ Lockdown Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Arced
☐ Others (Specify): Unknown Person Installed

8. Initial Value on 14" Olefins recovery pipeline (Specify)

Impact of Activities

A Properties Impacted by the activities

- ☐ Air Quality ☐ Noise Level ☐ Vegetation ☐ Fishery Resource ☐ Surface Water
☐ Water Quality ☐ Other Property

B Extent of Impact

- ☐ All natural vegetation ☐ All natural fishery resources ☐ Local fishery income
☐ Local fishery value ☐ Disturbance of vegetation ☐ Other Property

C Determination of Impacted Area

- ☒ Rubber Company's facility (R/CW) ☐ Gunter Company's facility (R/CW)

D Extent of Impact

(a) Community (Indigenous people)

(b) Local (Indigenous people)

- i. ...
 ii. ...
 iii. ...
 iv. ...

(c) Local (Indigenous people)

☐ Total

☐ Non-Total

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Total

☐ Non-Total

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Total

☐ Non-Total

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline water

☐ Total

☐ Non-Total

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

SPDC should increase surveillance
To avoid such kind of incident in - for
facilities

12. Time Investigation ended

13. Name and Signature of Participants

❖ NOSDRA

1. Ugbah Henry in  07-05-2017

2.

3.


❖ DPR

1. ALEXANDER ABUSAKA  02/05/2019

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Ameechi Stella  7/5/19

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. Chukwu Mamechom  7/5/19

2.

3.

❖ COMMUNITY

1. Emmanuel Chidihere  7/5/19

2.

3.