

PHOTOGRAPH TAKEN DURING JIV



AN AREA VIEW OF THE SPILL POINT BEFORE EXCAVATION.



Figure 2 SOURCE OF THE LEAKAGE FROM THE FAILED CLAMP (2) AFTER EXCAVATION.



Figure 1 TWO CLAMPS SECTIONED ON THE AFFECTED PIPE LINE (1&2) AFTER EXCAVATION.



The spill point backfilled and boom used as structural control in place.