

PHOTOGRAPHS TAKEN ON SITE



FIG A: Incident point on arrival



FIG B: Incident point on exposure



FIG C: Incident point after repairs (patch plating)



FIG D: Incident point after repairs