



PIC: SHOWING INCIDENT POINT BEFORE EXCAVATION (NON-LEAK POINT)



PIC: SHOWING POINT AFTER EXPOSURE (2" BALL VALVE AND 2 CALVANIZED PIPE WITH ELBOW AT 12'O
CLOCK POSITION ON THE PIPELINE)