

PHOTOGRAPHS TAKEN DURING THE JOINT INSPECTION VISIT



FIG. A: SHOWING A 3” FLANGE INSTALLED AT 12 O’ CLOCK POSITION OF THE PIPELINE



FIG B: SHOWING CRUDE STAINED AND WEATHERED VEGETATION AT THE IMPACTED AREA