

PHOTOGRAPHS TAKEN DURING THE JIV AT ETELEBOU FLOW STATION



FIG. A: THREE QUARTER PIPE THAT SPILLED OIL



FIG. B: THE SERVER PIT ROM WHERE OIL ESCAPED



FIG. C: TREATED WATER DISCHARGE PIPE OPENING



FIG. D: VEGETATION IMPACTED BY CRUDE OIL



FIG. E: STRECH OF WATER AND LAND IMPACTED BY CRUDE OIL