

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A & B: Incident Area on arrival of the JIT and green vegetation



Fig C: Incident facility after exposure



Fig D: 4" nipple/valve installed by Vandals