



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

Company: ENAGEED RESOURCE LIMITED

Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

Incident Details

- i. Date of Incident: 14/07/2020 ii. Date first reported: 15/07/2020
iii. Date of first investigation: 17/07/2020 iv. Spill Incident No: ERL/MI48/HSSSE/NO5/2020/025
v. Date of follow-up investigation:
vi. Time investigation started: 01:30 PM
vii. Estimated quantity spilled(bbls): 7 viii. Quantity Recovered: NIL

4. Site Details

- i. Site/Location: 6" CRUDE OIL EXPORT LINE AT TP7-8 AJATITON
ii. State: EDO iii. L.G.A: IKPOBA - OKHA
iv. Spill Co-Ordinates: N(m) 06° 5' 21"
E(m) 005° 30' 16"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NONE

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
- ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) EXPORT LINE
- iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
- v. Visible Sign of Third Party Interference
☐ Jigsaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid



☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☒ Others NONE

8. Extent of Impact

a) Community (indicate name)

i.
ii.
iii.
iv.

b) Land (indicate area in m²)

i.
ii.
iii.
iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

--	--	--	--

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation IMMEDIATE REPAIR OF THE DAMAGED EXPORT LINE, IMMEDIATE CLEAN UP OF THE IMPACTED AREA AND INTENSIFY SURVEILLANCE

13. Time investigation ended 04:30 PM