


*PHOTOGRAPHS TAKEN DURING JIV AT 6" Deep 6 Ogboinbiri Flowline At Ogboinbiri
In Southern Local Government Area Of Bayelsa State.*



GASEOUS EMISSION FROM SPILL POINT



THREE HACKSAW CUTS ON THE FLOWLINE



REPAIR POINT (WRAPPED)

WITHERED VEGETATION