

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: Incident Facility (Clough Creek 2 Manifold)




Fig B: Hacksaw cut inflicted by Vandals



Fig C: Vandalized 4\" Gas F/L



Fig D: Adjoining Environment/Green Vegetation