

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: Incident Area on arrival of JIT



Fig B: Incident Facility shortly after excavation



Fig C: Crude oil impact on the environment



Fig D: Incident facility during repair