

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: Incident Area on arrival of JIT



Fig B: Incident Facility shortly after excavation



Fig C: Oil spill impact



Fig D: NAOC's RoW/Impact



Fig E: Incident Facility during repair



Fig F: Incident Facility immediately after repair