

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: Incident Facility (Ogboinbiri Well 7 TBG)



Fig B: Rupture on the Well 7 choke box



Fig C: Oil Spill Impact