



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: N.A.O.C. 2021/LAR/049/079

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 19/06/2021 ii. Date first reported: 19/06/2021
iii. Date of first investigation: 20/06/2021
iv. Date of follow-up investigation:
v. Time investigation started: 15:34 hrs
vi. Estimated quantity spilled: 8 barrels

4. Site Details

- i. Site/Location: Offshore 155 Flowline at Offshore
ii. Position of Spill/Leak: see attached
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) Pit

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Unusually Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. 98line

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 1.250 m³

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... *NAOC should intensify surveillance along the fault line*

12. Time Investigation ended..... *16:00 hrs.*

Incident No: 2021/LAR/049/079

Company: N AOC

Incident Date: 19/06/2021

SIN Date: 20/06/2021

Spill points Coordinates.

Longitude

Latitude

1. 006° 28' 57.1"	05° 06' 13.5"
2. 006° 28' 57.0"	05° 06' 13.5"
3. 006° 28' 56.8"	05° 06' 13.5"
4. 006° 28' 56.7"	05° 06' 13.4"
5. 006° 28' 56.4"	05° 06' 13.3"
6. 006° 28' 56.3"	05° 06' 13.3"
7. 006° 28' 56.2"	05° 06' 13.3"
8. 006° 28' 56.0"	05° 06' 13.2"
9. 006° 28' 55.8"	05° 06' 13.1"
10. 006° 28' 55.5"	05° 06' 13.0"
11. 006° 28' 55.0"	05° 06' 13.0"