

AKINIMA 2

2021/LAR/066

N05° 05' 54.3"
E006° 27' 41.7"

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Agip Oil Company (NAOC)
2. Type of Complaint/Incident:
 - ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify) Condensate
3. Incident Details
 - i. Date of Incident: 15-7-2021 ii. Date first reported: 15-7-2021
 - iii. Date of first investigation: 16-7-2021
 - iv. Date of follow-up investigation:
 - v. Time investigation started: 3:20 pm
 - vi. Estimated quantity spilled: 0.175 barrels
4. Site Details
 - i. Site/Location: Oshie 9L Flowline at Akinima, Abiodun West Loc River state
 - ii. Position of Spill/Leak: 4 - 7 O'clock position
100m hacksaw cut
 - iii. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify)
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Fences ☐ Bund wall ☐ Sorbents ☒ Others (specify) Contained in a pit excavated by third party
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock ☒ 7 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause Of Spill
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify)
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify)