

PHOTOGRAPHS TAKEN ON SITE



FIG A: Incident point on arrival



FIG B: Incident area environment



FIG C-D: Incident point on exposure



FIG E-F: Incident point after repairs

