

PHOTOGRAPHS TAKEN ON SITE



FIG A-C: Impact around the NAOC Terminal and dockyard area



FIG D-E: NAOC alleged incident area showed no evidence of oiling



FIG F: Debris collected



FIG G: Incident point



FIG H: Sample collection at dock area



FIG I: Impact on the Brass Canal



Fig J-K: Impact along community waterfront and creek

