



NO TRACE OF OIL AT THE SPILL POINT.



3" VALVE INSTALLED ON THE FACILITY.



THE POINT AFTER PATCH WELDING.



SPILL POINT REPAIRED AND WRAPPED.