



Pictures 1&2 showing installed valve at spill point and repaired point.