


**PHOTOGRAPHS TAKEN DURING JIV AT 6" OGBOINBIRI/TEBIDABA PIPELINE AT OKPOTUWARI
IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE**



SPILL POINT BEFORE EXCAVATION



SPILL POINT



REPAIR POINT



IMPACTED AREA