

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI/TEBIDABA PIPELINE AT IKEBIRI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT (1"galvanize pipe with hose connected to the 3" valve at 12 O'clock position on the 14" pipeline)



REPAIR POINT



ARITISAN REFINERY CAMP



IMPACTED AREA