

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 6" OGBOINBIRI/TEBIDABA PIPELIE AT IKEINGHENBIRI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT (*Before excavation*)



SPILL POINT (*After excavation: Installed 2" ball valve
At 12 O'clock position on the pipeline*)



REPAIR POINT



IMPACTED AREA