


APPENDIX A:
 PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI/TEBIDABA PIPELIE AT IKEINGHENBIRI IN
 SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT (*Before excavation*)



SPILL POINT (*After excavation: Installed 3" ball valve
 At 12 O'clock position on the pipeline*)



REPAIR POINT



IMPACTED AREA