

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI/TEBIDABA PIPELINE AT IKEINGHENBIRI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT (Before excavation)



SPILL POINT (After excavation: Installed 3" ball valve
At 12 O'clock position on the pipeline)



REPAIR POINT



IMPACTED AREA