

LOCAL GOVERNMENT AREA, BAYELSA STATE.



FIG. 1: SHOWING CORROSION POINT AT 6 O' CLOCK POSITION.



FIG. 1: SHOWING UTM TEST BEING DONE ON THE PIPELINE.



FIG. 3: SHOWING CRUDE OIL ENTERING THE OPEN RIVER. FIG. 4: SHOWING CRUDE OIL IMPACT ON SURFACE WATER AND VEGETATION.

