

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT




Fig 1: Well 1s Flowline Valve (Incident Valve)




Fig 2: Contained Spill at the Flowstation



Fig 3: Well 3T



Fig: Well 3T Surrounding