

APPENDIX A

PHOTOGRAPHS TAKEN DURING JIV AT 18"TEBIDABA/BRASS PIPELINE AT ELEPA
SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



FIG: 1 CONTAINMENT BOOMS



FIG.2 SHOWING SPILLED CRUDE



Figure 3 SPILL POINT BEFORE EXCAVATION



Figure 4 SPILL POINT AFTER EXCAVATION



Figure 5 REPAIRED POINT