

Some Photographs taken during the Joint Investigation Visit (JIV)



Fig. 1
Incident Area on Arrival of the JIV



Fig. 2
Incident Facility Exposure/Impact



Fig. 3
The 4" Ball valve attached to the 24" for Oil Theft