

Some Photographs taken during the Joint Investigation Visit (JIV)



Fig. 1  
Incident Area on Arrival of the JIV



Fig. 2  
Incident Facility Exposure/Impact



Fig. 3  
The 4" Ball valve attached to the 16" for Oil Theft