

2022/LAR/203



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: N.A.O.C

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

i. Date of Incident: 17-11-2022 ii. Date first reported: 17-11-2022

iii. Date of first investigation: 17-11-2022

iv. Date of follow-up investigation: N/L

v. Time investigation started: 15:25 HRS

vi. Estimated quantity spilled: 12 bbls

4. Site Details

i. Site/Location: 18" EBOCHA - OGDA P/L @ EGBEE COMMUNITY. AHEAD LGA-R/S

ii. Position of Spill/Leak: N 05° 08' 05.5" E 006° 34' 26.2" N 05° 08' 06.6'

iii. Spill area E 006° 34' 26.2"

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 8 O'Clock ☐ 6 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 3 O'Clock ☐ 2 O'Clock

P1: 11-1 O'Clock

P2: 9-11 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

i. Properties Impacted by the Incident

☒ Farm/land ☒ Fish Pond ☒ Vegetation ☒ Fishing Boat ☒ Surface water
☒ Vegetable (Specify) ☒ Others (Specify)

ii. Nature of Impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead Hunting Fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delimitation of Impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

3. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. SLICK

i. 848,99 m²

ii.

ii.

iii.

iii.

iv.

iv.

(c) Creek/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... COMMENCE RECOVERY & CLEAN-UP
IMPACTED AREA ASAP.

12. Time Investigation ended..... 1:00 PM

13. Name and Signature of Participants

❖ NOSDRA

1. DAUNGIDE A-E [Signature] 17/11/2022

2.