



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 206 8193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		21 / 2022	
Section 2 - Location			
State / LGA		Yoho PP OML 104 - /	
Coordinates of spill		EASTINGS 4Deg 0Min/9Secs N NORTHINGS 7Deg 29Min/45Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		12/10/2022 Time: 12:40 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Other: Observed silvery sheen on the eastern side of Yoho YP after heavy rain, sheen traced to rain water wash-down of open skids (HP flare scrubber and water treatment system skids)	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify) Carried out further cleaning of skid to prevent reoccurrence.....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Sulphur Content		

	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00001 bbl of oily water based on sheen appearance		
	Coverage	About 5m x 4m of 50% silvery seen & 50% clear water		
	Direction of travel	East		

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	North East
Initial Wind Speed	6 knots
Air Temperature (C or OF)	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor
OCEANOGRAPHIC DATA	
Water Current Speed	
Tide Phase: Flood	High ☐ Ebb ☐
Water Temperature (OC or OF)	25 °C
High Tide Time	
Source	

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☒
Recovery of free phase oil	Yes ☐ No ☒
Booming	Yes ☐ No ☒
Wild life rehabilitation	Yes ☐ No ☒
Dispersant application	Yes ☐ No ☒

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)	

Section 8– Equipment	
On Site	

Section 8– Equipment	
On Site	

ForSL
REPORTING OFFICER: Mark Fraser.....

DESIGNATION: General Manager, Joint Venture Operations.....

SIGNATURE:  DocuSigned by:
6EC5DAC54B38492...

SIGNATURE:  DocuSigned by:
6EC5DAC54B38492...

SIGNATURE:  DocuSigned by:
6EC5DAC54B38492...

DATE: December 11, 2022

DATE: December 11, 2022

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*