

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....None.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... The Company should be mandated to initiate recovery of the oil and clean up the area with the Supervision of the Agency. They should be informed to intensify pipeline surveillance in their facilities.

12. Time Investigation ended.....1840 hrs.....