



PHOTOGRAPHS TAKEN DURING JIV AT 6" TEBIDABA WELL 14 FLOWLINE AT IKEBIRI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT BEFORE EXCAVATION



SPILL POINT



REPAIR POINT



IMPACTED AREA