

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 6" AZUZUAMA/TEBIDABA PIPELINE AT IKEBIRI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT BEFORE EXCAVATION



SPILL POINT



REPAIR POINT



IMPACTED AREA