


APPENDIX A:


PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI/TEBIDABA PIPELINE AT KEME-EBIAMA
IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE




SPILL POINT BEFORE EXCAVATION



SPILL POINT



REPAIR POINT



IMPACTED AREA