

2023-1007121



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

SPDC

1. Company:

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify): Illegal connections

3. Incident Details

i. Date of Incident: 27/03/2023 Date first reported: 27/03/2023

ii. Date of first investigation: 01/04/2023

iii. Date of follow-up investigation:

iv. Time investigation started: 12:05 HRS

v. Estimated quantity spilled: N/A

L.G.N, R/S

4. Site Details: 8" AGS-Rubber pipe 7m length at Elele Alimini, Anas

i. Position of Spill Tank: 5.054030N, 6.70251468E

ii. Spill area

☐ On land ☐ On water ☐ On shore ☐ On offshore (specify): Off-shore

iii. Structural Controls in Place: N/A

☐ Boom ☐ Trenches ☐ Bund wall ☐ Others (specify):

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Kerosene ☒ Others (specify): Black oil

☐ Others (specify):

iii. Facility

☐ Pipeline ☐ Low line ☐ Wellhead ☐ Manifold ☐ Low station ☐ Others (specify):

☐ Storage tank ☐ Compressor Plant ☐ Others (specify):

iv. Cause of spill

☐ Corrosion ☐ Equipment Failure ☒ Human Error ☐ Natural

☐ Operational Error ☐ Others (specify):

v. Visible Signs of Third Party Interference

☐ Blackness Marks ☐ Drilling Mud ☐ Blowing

☐ Others (specify): Drilling hole, 2" and 3" by 11 inches (diameter)

Installed on the line at 12 O' Clock position by unknown person.

6. Impact of Incident

i Properties impacted by the incident N/A

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact N/A ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Oil stained vegetation ☐ Withering of vegetation ☐ Others

☐ Dead floating crabs ☐ Delinication of impacted area N/A

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. Etela Kilima

ii.

iii.

iv.

b) Land (indicate area in m^2)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *Nil*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

*SPDC should ensure
SM of Security of the pipeline
↳ coastal fence secure.*