



1102362 (ETEO JIV)

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**JOINT INVESTIGATION VISIT (JIV) FORM***Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY (SPDC)

2. Type of Complaint Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 8/5/2023 ii. Date first reported: 9/5/2023
iii. Date of first investigation: 10/5/2023
iv. Date of follow-up investigation: 13/5/2025 (JIV DATE)
v. Time investigation started: ARRIVAL 2:15PM JIV TIME 5:05PM - 5:25PM
vi. Estimated quantity spilled: 1734 BARRELS

4. Site Details

- i. Site/Location: 28th NKPOKU-BOMU PIPELINE AT ETEO COMMUNITY, ELEME L.G.A. RIVERS STATE.
ii. Position of Spill/Leak: 1) LEAK POINT LAT. 4.75740N LONG. 7.16627E
2) NON LEAK POINT LAT. 4.75738N LONG. 7.16632E
iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)
iv. Structural Controls in Place MANUALLY MADE CONTAINMENT DITCH
☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- Theft point ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)
A ROAD CONSTRUCTION VEHICLE BELONGING TO SETRACO NIG. LTD. INFRINGED ON A PROTRUDING ILLEGAL CONNECTION MADE BY UNKNOWN PERSONS AT 12 O'CLOCK POSITION ON THE PIPELINE