

INC-NO-1266111

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S.P.R.C.

2. Type of Complaint/Incident:

☒ Oil Pollution☐ Fire/Explosion☐ Drilling Mud/Chemical Pollution☒ Others (Specify) NO SPILL

3. Incident Details

i. Date of Incident: 14/07/2023ii. Date first reported: 14/07/2023iii. Date of first investigation: 14/07/2023

iv. Date of follow-up investigation:

v. Time investigation started: 1550 Hoursvi. Estimated quantity spilled: NO SPILL

4. Site Details

i. Site/Location: 20" RUMUEKPE-NKPOKU TNP AT IBAAii. Position of Spill/Leak: N 4.95441381 E 6.81163383

iii. Spill area

☒ Land☐ Swamp☐ Freshwater☐ Mangrove☐ Coastline☐ Near shore☐ Offshore☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom☐ Trenches☐ Bund Wall☐ Sorbents☐ Others (Specify) 3 N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock☐ 10 O'Clock☐ 2 O'Clock☐ 3 O'Clock☐ 4 O'Clock☐ 5 O'Clock☐ 6 O'Clock

ii. Type of Oil Contaminant

☒ Crude Oil☐ Condensate☐ Chemicals☐ Refined Products☐ Others (Specify)

iii. Facility

☒ Pipeline☐ Flow Line☐ Wellhead☐ Manifold☐ Flow Station☐ Rig☐ Storage Tank☐ Compressor Plant☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion☐ Equipment Failure☒ Third Party Interference☐ Accident☐ Operational Error☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks☐ Drilled Holes☐ Blasting☒ Theft☐ Acid☒ Others (Specify) 3" BALL VALVE SEATED ON 3" FLANGE AT 12 O'CLOCK POSITION.

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

} N/A

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify)

} N/A

iii. Delineation of Impacted area

☐ Within Company's facility/ROW

☐ Outside Company's facility/ROW

} N/A

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

} N/A

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
NOT APPLICABLE			

9 Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10 Sample taken NOT APPLICABLE

11 Investigation carried out by

☒ Civil ☐ Fire ☐ Naval

12 Remarks/Recommendation SPDC TO CARRY OUT REPAIRS IMMEDIATELY AFTER JUV. IMPROVED SURVEILLANCE OF SPDC'S KEN SHOULD BE TAKEN SERIOUSLY

13 Time investigation ended 1630 Hours

14 Name and Signature of Participants