



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Mobil Producing Nigeria -MPN
Reporting Officer	Mark Fraser
Designation	General Manager, Joint Venture Operations
Phone Number	+2348172068193
Email Address	mark.w.fraser@exxonmobil.com
Incident Number	019 / 2023
Section 2 - Location	
State / LGA	Ubit PP OML 67 - / Akwa Ibom
Coordinates of spill	EASTINGS 4Deg 16Min/28Secs N NORTHINGS 8Deg 10Min/33Secs E
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	12/7/2023 Time: 15:30 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill	Corrosion: At about 15:30hrs, during sump tank inspection at the Compression Platform (GY), personnel observed oily water dripping to sea from a corroded 3-inch line (at the pipe support) from the fuel gas skid to the GY sump tank. A small patch of silvery surface was created on the sea. The fuel gas system had been bypassed and positively isolated during the 2022 Ubit SD.
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Drain pot directly connected to piping was covered to prevent further water ingress. Sheen dispersed naturally.

Product Data	☐ Persistent		☐ Non Persistent	
	Product Name/Type			
	SG/API Gravity			
	Pour Point			
	Wax Content			
	Asphaltene			
	Sulphur Content			
Oil	Slick Locations(s)			
observation	Slick Dimension(s)			
	Orientation of slick(s)			
	Distribution of oil			
	Obvious odour			
Oil descriptions	Tarballs (tb)			
	Convergence line (co)			
	No structure (ns)			
	Windrows (wr)			
	Streamers (st)			
	Patches (pa)			
Oil color and appearance	Silver/grey			
	Rainbow			
	Metallic			
	Transitional			
	Dark			
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....		
Section 4 – Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00001 bbl of Oily Water based on sheen appearance		
	Coverage	About 5m x 2m of 60% of clear water, 20% of rainbow colors and 20% of silvery sheen on the sea.		
	Direction of travel	South-West		
Section 5 - Weather				
METEOROLOGICAL DATA			NIMET weather forecast	
Wind Direction (wind direction given from)				
Initial Wind Speed				
Air Temperature (C or OF)				
Visibility Estimate		☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA				
Water Current Speed				
Tide Phase: Flood		High ☐ Ebb ☐		
Water Temperature (OC or OF)				
High Tide Time				
Source				
Section 6 – Pre-Entry Activities				
Mechanical cleaning		Yes ☐	No ☐	
Recovery of free phase oil		Yes ☐	No ☐	

Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐
Section 6 – Pre-Entry Activities		
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐ Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser

DESIGNATION: General Manager, Joint Venture Operations

DS
1E

DocuSigned by:

Mark W. Fraser

E80C423DA74246A...

SIGNATURE:

December 8, 2023

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*