



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		025 / 2023	
Section 2 - Location			
State / LGA		Ubit PP OML 67 - / Akwa Ibom State	
Coordinates of spill		EASTINGS 4Deg 16Min/45Secs N NORTHINGS 0Deg 13Min/40Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		12/28/2023 Time: 06:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☒ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment Failure: FSV Elyon on patrol duties at Mfem A reported sighting possible sheen at location coming from the well head. O&M visited location and stopped leaks from fouled instrumentation.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Insolated instrument air system to equipment as the platform is currently shutdown	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		

	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
Oil color and appearance	Patches (pa)		
	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00035bbl of oily water based on sheen appearance		
	Coverage	About 85 % barely discernible; 5% light brown and 10% silvery sheen on sea water.		
	Direction of travel			

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	West	NIMET weather forecast
Initial Wind Speed	5knots	
Air Temperature (C or OF)	36°C	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wildlife rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☒	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	--	---	---

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser
DESIGNATION: General Manager, Joint Venture Operations

DS
IE

SIGNATURE:
 DocuSigned by:
 David McLeod
 150704B3DE2A47D.....

December 28, 2023
DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*