



JOINT INVESTIGATION VISIT (JIV) FORM

1. Company: Chevron Nigeria Limited (CNR)

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....OTP.....

i. Date of Incident: 13 Jan 2024 ii. Date first reported: 21 Jan, 2024

iii. Date of first investigation: 25 January 2024

iv. Date of follow-up investigation:.....

v. Time investigation started:..... 15:09 HOURS

vi. Estimated quantity spilled:.....

i. Site/Location: 005° 01' 29.6 E 12 Openkeba / Ona Pipeline

ii. Position of Spill/Leak:.....

☐Land ☒Swamp ☐Freshwater ☐Mangrove ☐Coastline
☐Near shore ☐Offshore ☐Others (specify).....

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 4 inch Valve welded illegally on.

(specify) 4 inch Valve welded illegally on the
12" Openkeba/Oloro pipeline @ 12' O'clock position

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others... *Oil Sheen on Surface Water*

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... NONE

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation

(i) CNL should intensify surveillance along that line as third party interference is becoming too rampant.
(ii) The illegally welded valve should be removed and repaired and properly covered up to prevent subsequent oil theft

12. Time investigation ended

15:39 HOURS

✓iii Dredging / Opening-up of the ROW should be done as soon as possible to give free access to security and community surveillance for proper monitoring of the afore-mentioned pipeline