



National Oil Spill Detection and Response Agency
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name	EXXON MOBIL, FRONTIER OIL LTD., UNIVERSAL ENERGIES RES. LTD., NETWORK E&P		
Incident Number			
Type of Complaint/Incident	☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☒ Others (specify) patches of unidentified substance		
Incident Details			
Date of Incident	31/02/2023		
Date first reported	01/01/2024		
Date of first investigation	01/01/2024 by NOSDRA & A&S		
Date of follow-up investigation	03/01/2024		
Time of investigation	14:13 HRS		
Estimated quantity spilled	Yet to be determined		
Site Details			
Facility Address	N/A		
Position of Spill/Leak	N/A		
Location	GPS Coordinate		N E
OML:			
Spill Area			
	☐ Land ☐ Swamp ☐ Fresh Water ☐ Mangrove ☒ Coastline ☐ Nearshore ☐ Offshore ☐ Others observations around the spill point (specify).....		
Structural Controls in Place	☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☐ Others (specify).....		
Circumstances Around Spill point			
Visual Observation of Hole Point	☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock		
Type of Contaminant	☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products ☐ Others (specify)..... yet to be determined		
Facility	☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....		
Cause of spill	Company ☐ Corrosion ☐ Equipment Failure ☐ Operational/Maintenance Error ☐ Bund wall overflow	Third Party Interference ☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☐ Others	Others ☐ Accident ☒ Mystery

Additional Description of
Spill Point

N/A

- ☐ Hacksaw Marks
- ☐ Hacksaw cut
- ☐ Theft (illegal bunkering)
- ☐ Valve failure
- ☐ Missing Pipeline/Flowline
- ☐ Failed Clamp
- ☐ Well head tampering
- ☐ Failed clamp
- ☐ Bulging outward
- ☐ Complete rupture

- ☐ Drilled Holes
- ☐ Blast
- ☐ Flare System/Bund wall failure
- ☐ Saver pit overflow
- ☐ Third party tampering with valve setting
- ☐ Third party tampering with flange
- ☐ Inward dent
- ☐ Surge vessel overflow
- ☐ Relief valve failure
- ☐ Others (specify).....

Graphic Description of Leak Point (sketches/illustrations)



Shoreline/water			
☒ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
RT TANK FARM AREA			
ESUK IKIM EICEME			
NDIOKA IBA			
ITAK IFAHA			
Photograph/Map/Chart Ref.		☒ Still Photograph ☐ Video coverage ☐ Mapping	
Samples taken	Samples of the unidentified patches taken		
Investigation	☒ Foot ☐ Boat ☐ Aircraft ☐ Drone		

REMARKS/RECOMMENDATION

- ① THE OBSERVED PATCHES ON THE SHORELINE NEEDS TO BE CLEANED UP TO ENHANCE BEACH AESTHETICS FROM RT TANK FARM AREA TO ITAK IFAHA AND BEYOND IDENTIFIED AREA
2. CONCLUDE FINGER ANALYSES ON SAMPLE TO IDENTIFY CULPRIT

DATE/TIME INVESTIGATION ENDED 14:13 HRS / 03/01/2024

Name and Signature of Participants					
NOSDRA			Local Government Council		
S/N	Name	Signature	S/N	Name	Signature
1.	ODUNGIDE A E		1.	Hon Herson ELOA	
2.	GAXTON OKORAH		2.	DR GEDION ROBAT	
3.			3.		
DEP			Company		
1.			1.	Veronica Akpan-FOLAN	
2.			2.	ADESAYO OLUFEMI	
3.			3.	IBORO AKPAN-UGRI	
State Ministry of Environment			Community		
1.	Engr. Aniche Emah		1.	Anthony C. Ejiro	
2.			2.	Kenneth E. Ike	
3.			3.		

Com.

NIERNL
I.X.C. Chom