

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... SPDC should intensify surveillance
along the right of way to avoid future occurrence.
and carry out immediate repair on the damaged pipeline.

12. Time Investigation ended..... 2:30 pm

13. Name and Signature of Investigator.....