



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		Mark.w.fraser@exxonmobil.com	
Incident Number		006 / 2024	
Section 2 - Location			
State / LGA		Ubit PP OML 70 - /	
Coordinates of spill		EASTINGS 4Deg 14Min/27Secs N NORTHINGS 8Deg 8Min/24Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		3/31/2024 Time: 10:50 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment Failure: - On March 31, 2024, during platform checks by Mediator II (FSV) between 1044hrs – 1051hrs, oily sheen was reported around Ubit GC platform 100*T / East direction measuring about 5M by Infinite.- Ubit operations personnel were dispatched and arrived location at about 11:15hrs.- Observed oily water drips to sea from the sump tank overflow line resulting in oily patches and silvery surface on the sea	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify).....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		

	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release		Continuous Release		
			Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00006bbbls of Oily Water based on sheen appearance			
	Coverage	About 5.5m X 3m of 5% light brown and 95% silvery sheen on sea water.			
	Direction of travel	North East			

Section 5 - Weather

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	Northeast	
Initial Wind Speed	4.31965knots	
Air Temperature (C or OF)	34°C	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☒	No ☐
Recovery of free phase oil	Yes ☐	No ☒
Booming	Yes ☐	No ☒

Wild life rehabilitation	Yes ☐	No ☒
Dispersant application	Yes ☐	No ☒
Section 6 – Pre-Entry Activities		
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐ Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: For: **Mark Fraser**

DESIGNATION: **General Manager, Joint Venture Operations**

DocuSigned by:

ETABUKO ABIRHIRE

ETABUKO ABIRHIRE

April 1, 2024

SIGNATURE:A7C7F31414DC467.....

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*