


APPENDIX A



On arrival at the incident point.



Incident point with 2" valve installed.



Repaired incident point