



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: HERITAGE ENERGY OPERATIONAL SERVICES LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 15 / 07 / 2024 ii. Date first reported: 15 / 07 / 2024
iii. Date of first investigation: 21 / 07 / 2024 iv. Spill Incident No: HEOSL/2024/270
v. Date of follow-up investigation:
vi. Time investigation started: 3:50 PM
vii. Estimated quantity spilled(bbls): viii. Quantity Recovered:

4. Site Details

- i. Site/Location: 28" TRANS FORCADOS PIPELINE (TFP) AT YEYE
ii. State: DELTA iii. L.G.A: BURUTU
iv. Spill Co-Ordinates: N(m) 05° 27' 16.34"
E(m) 005° 24' 02.71"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Frenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock ☒ 8 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock ☐ 9 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility


- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

- ☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☒ Others (specify) A HOLE OF 0.3 mm

v. Visible Sign of Third-Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) NOT APPLICABLE



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☒ Others (specify) SHORE LINE

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. YEYE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>SUNYMA CREEK</u>			

c) Swamp

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>YEYE</u>			
0			

d) River

☒ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>YEYE RIVER</u>			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken NONE

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. HERITAGE ENERGY OPERATIONAL SERVICE
LIMITED SHOULD CARRY OUT A SECTIONAL REPLACEMENT,
IMMEDIATELY CLEAN UP THE IMPACTED AREA WHICH SHALL BE MONITORED BY
THE AGENCY. ALSO CARRY OUT A DAMAGE ASSESSMENT.

13. Time investigation ended.....

14. Name and Signature of Participants