

PICTORIAL REPORT OF JOINT INVESTIGATION VISIT (JIV) TO SK BRIGHT FILLING STATION AT ARAROMI STREET, AKURE SOUTH LOCAL GOVERNMENT AREA OF ONDO STATE, HELD ON TUESDAY JULY 23, 2024.



Fig 1: Well-1 appears visibly unpolluted with hydrocarbon.



Fig 2: Well-2 appears visibly not contaminated with hydrocarbon.




Fig 3: Well-5 suspected to be polluted with PMS.




Fig 4: Well-5 at a closer view



Fig 5: Well 3 appears not physically contaminated.



Fig 6: Well 4 looks physically unpolluted




Fig 7: PMS UST Point




Fig 8: physically clean from SK Fuel Station



Fig 9: Elevation profile of inspected Wells around SK Fuel Station.



Fig 10: Drainage channel free of sheen



Fig 11: A view of SK Fuel station forecourt.