

3671979



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
 - ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify) Non-Leak
3. Incident Details
 - i. Date of Incident: 15/09/2024
 - ii. Date first reported: 15/09/2024
 - iii. Date of first investigation: 27/10/2024
 - iv. Date of follow-up investigation:
 - v. Time investigation started: 12:23 HRS
 - vi. Estimated quantity spilled: NIL
4. Site Details
 - i. Site/Location: 20" Rumokere-Nkporu PL at Mbodo-Anu, Ikwere LGA, Rivers State
 - ii. Position of Spill/Leak: N4° 55' 53.4686" E6° 58' 4.89868" N4° 55' 53.4686" E6° 58' 4.89868"
 - iii. Spill area
 - ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (Specify)
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
 - ☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock
 - ii. Type of Oil Contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (Specify) NO SPILL
 - iii. Facility
 - ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant
 - ☐ Others (Specify)
 - iv. Cause of Spill
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (Specify)
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
 - ☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) No spill

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify) No spill

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. Mbodo-Aluy
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i. None
ii.
iii.
iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken... None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aerial

11. Remarks/Recommendation. NOSDRA mandated SPDC to commence repairs immediately.
SPDC should remove double 2" ball valves installed on its facility by unknown persons.
SPDC should enhance surveillance on its facility.

12. Time Investigation ended... 13:28 HRS