

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken

No

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

*Immediate repair of the
damaged portion of the pipeline.
Security on the right of way should be intensified*

12. Time investigation ended

14:25 Hrs

13. Name and Signature of Participants

◆ NOSDRA

7-1-1-1-1-1-1-1-1-1